

GV 52-3 Follow up

Inspection Doc# 675202211

Erosion of road side. 2/4/15



Same area with erosion and
sediment migration.
11/19/15



Failed BMP with sediment
migration. 2/4/15



Same failed BMP. 11/19/15

