



**Photo 1:** Photo taken from Northern side of location facing South. Photo of interim reclamation. These areas need to be minimized and reclaimed.



**Photo 2:** Photo taken on northwest side of location, facing east. Photo of interim reclamation. Note the lack of perennial vegetation.



**Photo 3:** Photo taken on north end of location. Photo of gravel remaining on interim portion of location.



**Photo 4:** Photo taken from north side of location, facing North. Photo of Russian thistle weed debris, and gravel.



**Photo 5:** Photo taken from northeast side of location, facing west. Photo of interim reclamation. Note the lack of perennial vegetation. Vegetation in photo predominantly Russian thistle.



**Photo 6:** Photo taken from northeast side of location, facing south.



**Photo 7:** Photo taken from east side of location. Photo of trash on location, appears to be cable.



**Photo 8:** Photo taken from southeast side of location, facing North. Photo of interim reclamation. Vegetation predominantly Russian thistle and Kochia weed debris.



**Photo 9:** Photo taken from southeast side of location, facing west.



**Photo 10:** Photo taken from southwest side of location, facing North. Photo of interim reclamation. Note the lack of perennial vegetation.



**Photo 11:** Photo taken from southwest side of location, facing east.



**Photo 12:** Photo taken from well on location. Photo of weed debris in equipment.