



Photo 1: Photo taken from southwest portion of location facing north. Note the lack of perennial vegetation. Vegetation primarily Russian thistle.



Photo 2: Photo taken from southwest portion of location, facing east. Note the lack of perennial vegetation. Vegetation primarily Russian thistle.



Photo 3: Photo taken from western side of location. Photo shows crack forming on slope, this is an indication of soil erosion occurring on slope.



Photo 4: Photo taken from northwest portion of location facing south. Photo shows lack of perennial vegetation. Vegetation predominantly Russian thistle.



Photo 5: Photo taken from northeastern part of location facing east. Photo shows lack of perennial vegetation.



Photo 6: Photo taken from northern end of location. Photo of weed debris.



Photo 7: Photo taken from northeastern part of location, facing west. Photo shows lack of perennial vegetation. Vegetation predominantly Russian thistle.



Photo 8: Photo taken from southeastern part of location, facing south. Photo shows lack of perennial vegetation.



Photo 9: Photo taken from southeastern part of location, facing north.



Photo 10: Photo taken from southeastern part of location, west. Photo shows lack of perennial vegetation on interim reclamation area.