

**FORM INSP**  
Rev 05/11

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:  
11/10/2015

Document Number:  
680100297

Overall Inspection:

**ALLEGED VIOLATION**

**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____
	<u>382886</u>	<u>382886</u>	<u>Colby, Lou</u>		

**Operator Information:**

OGCC Operator Number: <u>80530</u>
Name of Operator: <u>SNYDER OIL CORP</u>
Address: <u>840 GESSNER STE 1400</u>
City: <u>HOUSTON</u> State: <u>TX</u> Zip: <u>77024</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Bower-Moore, Dru	307 347 4477	Dru.Bower-Moore@dvn.com	Sr. Regulatory Advisor
Ash, Margaret		margaret.ash@state.co.us	
Gaylan Bunas	(405)552-4594	Gaylan.Bunas@dvn.com	Regulatory Compliance
CYNTHIA J 228-8856	405 228 8856	cindy.chiba@dvn.com	Insurance Management

**Compliance Summary:**

QtrQtr: SESE Sec: 17 Twp: 6S Range: 90W

**Inspector Comment:**

Reclamation and Stormwater focused Inspection. Inspected as Reclamation Priority 80. APD expired 2/26/82. Latest Form 4 (Doc# 430245) on record submitted 9/30/83 is for Change Plans: "Location built, Well will not be drilled until Geologic evaluation complete. Will repermit if, when decision made to Drill." Open complaint in COGCC Records, filed 6/8/12 by Landowner referring to three Locations on property that have not been reclaimed. Landowner states that Operator Representative (Devon Energy) had a site visit, accepted responsibility for reclaiming the three Locations, but never carried through with any reclamation. Same conditions exist at location today as were documented in Alleged Violation Inspection 7/14/12, (Doc#668500087), except that Landowner has controlled Noxious weeds. Corrective Action date continues to reflect previous inspection unexecuted CA date, 10/16/12.

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
210633	WELL	AL	01/01/1999	GW	045-06389	SNYDER-BARTON PORTER 1-17	ND	<input checked="" type="checkbox"/>

**Equipment:**

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

Emergency Contact Number (S/A/V): \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Inspector Name: Colby, Lou

Corrective Action: \_\_\_\_\_

<b>Spills:</b>				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Venting:</b>	
Yes/No	Comment

<b>Flaring:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 382886

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/A/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 210633    Type: WELL    API Number: 045-06389    Status: AL    Insp. Status: ND

**Environmental**

**Spills/Releases:**  
 Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
 Comment:   
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
 Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
 Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:** \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_  
 DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location:

<b>Complaint:</b>				
Tracking Num	Category	Assigned To	Description	Incident Date
200353925	RECLAMATI ON	Spry-O'rourke, Linda	<p>On June 8 a member of the Porter family, Travis, visited the COGCC Rifle office with the basic information in the email, below. Jay Krabacher recorded the following information at that time.</p> <p>He and I pulled up the three wells on COGIS and I noted that Soraya had inspected all of them.</p> <p>The API #s for these 3 are                      045-06389 (Snyder-Barton Porter 1-17)                      045-06388 (Snyder Barton Porter 2-21)                      045-06350 (Snyder Barton Porter 1-16)</p> <p>Even though COGIS may list these as "PA" or "AL" Mr. Travis Porter claimed that the locations are not adequately nor suitably reclaimed. Snyder is operator #80530. These three still are in/on COGIS with Snyder as responsible operator.</p> <p>Jay called Noble's Regulatory Manager, Linda Pavelka, in their Denver office. Ms. Pavelka told us that, yes, Noble had taken over (bought) Snyder operations – WEST OF DIVIDE CREEK – and that DEVON ENERGY (#68355) had taken over Snyder operations EAST OF DIVIDE CREEK.</p> <p>Jay emailed Ms. Pavelka in the event anyone might wish her assistance in confirming Noble's non-involvement with this matter.</p>	06/08/2012

Emission Control Burner (ECB): \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

- 1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_
- Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_
- Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_
- Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_
- Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_
- Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

- 1003 f. Weeds Noxious weeds? \_\_\_\_\_
- Comment: \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

- Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_
- Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_
- Access Roads Regraded **Fail** Contoured **Fail** Culverts removed \_\_\_\_\_
- Gravel removed \_\_\_\_\_
- Location and associated production facilities reclaimed **Fail** Locations, facilities, roads, recontoured **Fail**

Inspector Name: Colby, Lou

Compaction alleviation Fail Dust and erosion control \_\_\_\_\_  
Non cropland: Revegetated 80% Fail Cropland: perennial forage \_\_\_\_\_

Weeds present In Process Subsidence \_\_\_\_\_

Comment: Landowner has been controlling Noxious weeds noted in previous inspection. Operator should consult with Landowner on Weed control plan and take responsibility to control weeds during revegetation period.

Corrective Action: Perform Final Reclamation per COGCC 1004 Rules ASAP. Consult Landowner on Schedule of activities. Reclamation activities should commence no later than Spring 2016. Submit via Form 4 Reclamation Plan including detailed Schedule of Reclamation activities. Date 10/16/2012

Overall Final Reclamation Fail Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: SATISFACTOR  
Y Corrective Date: \_\_\_\_\_

Comment: No concerning erosion or stormwater issues. Location has been stabilized by volunteer vegetation.

CA: \_\_\_\_\_

Pits:  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Location is long past it's Final Reclamation procedures completion date as per COGCC Rules. Operator needs to immediately contact Area Reclamation Specialist to discuss intent and plans to move forward with reclamation.	colbyl	11/24/2015

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680100310	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3729447">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3729447</a>