



Photo 1. View of southern portion of the project area from the southeastern corner facing westward. Grasses such as smooth brome (*Bromus inermis*) and dropseed (*Sporobolus* sp.) are growing here.



Photo 2. View of western portion of project area from northwestern corner facing southward. Berm appears to be in good condition. However, vegetation on the berm is largely kochia (*Kochia scoparia*) and cheatgrass (*Bromus tectorum*).



Photo 3. View of project area from northwestern corner facing center.



Photo 4. View of erosion in southern portion of project area that appears to be eroding off of facilities area. This should be monitored and repaired if it worsens.