



Photo 1. View of northern portion of the project area from northeastern corner facing westward. An infestation of Canada thistle (*Cirsium arvense*) and musk thistle (*Carduus nutans*) is present.



Photo 2. View of project area from the southwestern corner facing center.





Photo 3. View of where stormwater diversion is eroding in northwestern corner of the project area. Erosional channel is approximately 2 feet wide and 1 foot deep. Stormwater BMPs are needed to de-energize and filter stormwater flows in this area.





Photo 4. Another view of diversion channel that is eroding in northwestern portion of the project area. Stormwater BMPs are needed here.





Photo 5. View of a cluster of Canada thistle plants growing within the northern portion of the interim reclamation area.





Photo 6. View of approximately 23 musk thistle rosettes growing within the northern portion of the interim reclamation area.





Photo 5. View of approximately 10 musk thistle rosettes growing within the southern portion of the interim reclamation area. Noxious weeds are growing throughout the interim reclamation area.