



Photo 1. View of erosional channel approximately 1 foot wide and one foot deep eroding off of the northeastern portion of the project area .





Photo 2. View of approximately 17 musk thistle (*Carduus nutans*) within the interim reclamation area.





Photo 3. Another view of dense musk thistle rosettes within the interim reclamation area.





Photo 4. View of diversion channel that is eroding in northwestern portion of the project area. This portion of the project area needs stabilization measures and stormwater BMPs.





Photo 5. Another view of stormwater erosion in the northwestern corner of the project area (approximately 2 feet wide and 1.5 feet deep).



Photo 6. View of western portion of the project area from the northwestern corner facing southward.





Photo 7. View of the southern portion of the project area from the southwestern corner facing eastward.



Photo 8. View of stormwater erosion in the southern portion of the project area. Appears to be carrying sediment off of the project area.