



Photo 1: Photo taken from east of location facing west. Photo shows construction location. Topsoil berm on left of location. Note no defined access road or vehicle tracking BMPs in place to minimize disturbance and control sediment displacement by vehicles and/or equipment.



Photo 2: Photo taken east of location facing west. Note no defined access road or vehicle tracking BMPs in place to minimize disturbance and control sediment displacement by vehicles and/or equipment.



Photo 3: Photo taken from east end of location, facing north. Photo shows stormwater control ditch.



Photo 4: Photo taken from northeast corner of location, facing south. Photo shows stormwater control ditch.



Photo 5: Photo taken from northeast end of location, facing west. Photo shows stormwater control ditch.



Photo 6: Photo taken from northwest corner of location, facing south. Photo shows stormwater control ditch.



Photo 7: Photo taken from southwest corner of location, facing north. Photo shows stormwater control ditch.



Photo 8: Photo taken from northwest end of location facing east. Photo of topsoil berm.



Photo 9: Photo taken from north end of location, facing east. Photo of topsoil berm and stormwater ditch.



Photo 10: Photo taken from southeast end of location, facing southeast. Photo show insufficient stormwater BMPs in southeast corner of location.



Photo 11: Photo taken from southeast end of location, facing east. Photo show insufficient stormwater BMPs in southeast corner of location.