



Photo 1. View of an area in the eastern portion of the project area where it appears vegetation was recently scraped. Surface owner said BP has scheduled to seed this and other spill-affected areas in spring 2016.



Photo 2. View of stormwater BMP in northeastern corner of project area. Sediment is accumulating here and it appears to need maintenance. If concentrated flows downstream of this area worsen, additional BMPs will be needed.



Photo 3. View of stormwater erosion in the western portion of the project area from the northwestern corner facing southward (upstream).



Photo 4. View of stormwater erosion where flows exit the northwestern corner of the project area (downstream).



Photo 5. View of the southern portion of the project area from the southwestern corner facing eastward. Good cover of grasses such as intermediate wheatgrass (*Thinopyron intermedium*).



Photo 6. View of project area from the southwestern corner facing center.



Photo 7. View of the western portion of the project area from the southwestern corner facing northward.