



photo 1: Facing north along the access road towards the location.



photo 2: Facing northeast, access road continues north past the location.



photo 3: Southwest side of the location facing northeast




photo 4: Manure has been spread throughout the location



photo 5: Northwest side of the location facing east.



photo 6: Southwest side of the location facing west.



photo 7: North side of the location. The two wire strand fence is down low to the ground.



photo 8: Northwest corner, weed debris is beginning to accumulate along the fence line.