



photo 1: Facing southeast along access road towards the location.



photo 2: Northwest corner of the location facing southeast.



photo 3: Manure pile near the center of the location.



photo 4: Facing southeast at the location.



photo 5: Facing east towards the location. Manure has been applied to disturbed areas.



photo 6: Manure has been applied to disturbed areas.



photo 7: South side of the location facing north.



photo 8: Fence along south side of the location. Weed debris is accumulating along the fence line.