



Photo 1: Photo taken from west of location facing east. Photo shows well location.



Photo 2: Photo taken from northwest end of location, facing east. Photo shows stormwater control ditch.



Photo 3: Photo taken from southwest corner of location. Photo shows guy line anchor and marker.



Photo 4: Photo taken from southern end of location, facing south. Photo of Scotch thistle.



Photo 5: Photo taken from southern end of location, facing south. Photo shows insufficient stormwater BMPs, and rill erosion.



Photo 6: Photo taken from northeast end of location facing east. Photo shows stormwater BMP on northern end of location.



Photo 7: Photo taken from south end of location, facing north. Photo shows insufficient stormwater BMPs, and rill erosion (indicated with arrow). Photo shows Scotch thistle.



Photo 8: Photo taken from south end of location, facing north. Photo shows insufficient stormwater BMPs, and rill erosion (indicated with arrow). Photo shows Scotch thistle.



Photo 9: Photo of tank batter location sign.



Photo 10: Photo taken from west end of tank battery location, facing east.



Photo 11: Photo taken from west end of tank battery location, facing east. Photo of stormwater ditch.



Photo 12: Photo taken from east end of tank battery location, facing west.
Photo of stormwater ditch.



Photo 13: Photo taken from north end of tank battery location, facing west. Photo of stormwater ditch.



Photo 11: Photo taken from northwest end of tank battery location, facing south. Photo of stormwater ditch.