



Photo 1. View of the southern portion of the well pad from the southeastern corner facing westward. This portion of the well pad appears to have been recently prepared for interim reclamation. Fill slopes are still present and recontouring needs to be completed.



Photo 2. View of project area from the southeastern corner of the project area facing center.



Photo 3. View of the eastern portion of the project area from the southeastern corner of the project area facing northward. Vegetation on the right is from the interim reclamation area.



Photo 4. View of the western portion of the project area from the southwestern portion of the project area facing northward. Piles of rock and gravel are present and location has not been recontoured.