



Photo 1. View of the eastern portion of the project area from the southeastern corner facing northward. Musk thistle from the previous season can be seen in the mid-ground.



Photo 2. View of project area from the southeastern corner facing center. Pipeline riser in foreground needs removal. The well pad has been contoured and is currently furrowed.





Photo 3. View of the southern portion of the project area from the southeastern corner facing westward. Access road on left leads to 083-06637 location that was also recently plugged and abandoned.



Photo 4. Birdseye view of soil surface on well pad in process of reclamation. It does not appear that seeding has been completed.





Photo 5. View of pipe debris within the northwestern portion of the project area.