

# Stormwater and Construction Inspection

Inspection 1 of 2

12/02/2015

Operator: Wiepking-Fullerton

Location ID: 443145

API #: 05-073-06697

Lincoln County, CO

Section 2 T6S R54W

Aaron Trujillo  
Reclamation Specialist  
COGCC



**Figure 1:** Photo of sign for Loc. ID 443145, on northern end of location



**Figure 2:** Photo taken from County Road 0 facing south. Photo shows access road entrance.



**Figure 3:** Photo taken from access road entrance, facing south.



**Figure 4:** Photo taken from access road entrance, facing north.



**Figure 5:** Photo taken from northern area of location, facing west. Photo shows insufficient stormwater BMPs on northwest portion of location prior to construction activities.



**Figure 6:** Photo taken from northwest corner of location, facing east. Photo shows insufficient stormwater BMPs for site prior to construction activities. .



**Figure 7:** Photo taken from northwest corner of location, facing south. Photo of topsoil berm being constructed. Photo shows insufficient stormwater BMPs for site on western end of location prior to construction activities.



**Figure 8:** Photo taken from western end of location, facing north. Photo of topsoil berm being constructed. Photo shows insufficient stormwater BMPs for site on western end of location prior to construction activities. .



**Figure 9:** Photo taken from western end of location, facing south. Photo shows insufficient stormwater BMPs for site on western end of location. Note location appears to be built within a drainage. Arrows indicate direction of slope.



**Figure 10:** Photo taken from southwest corner of location, facing north. Photo shows insufficient stormwater BMPs for site on western end of location. Note location appears to be built within a drainage. Arrows indicate direction of slope.



**Figure 11:** Photo taken from southwest corner of location, facing east. Photo of construction in process.




**Figure 12:** Photo taken from southeast corner of location, facing west.




Stormwater  
control berm.

**Figure 13:** Photo taken from southeast corner of location, facing north. Photo of stormwater diversion berm on east end of location as per operator BMP.



**Figure 14:** Photo taken from stormwater control berm on east end of location, facing north. Photo of adequate surface roughening BMP up slope of stormwater control berm..



**Figure 15:** Photo taken from northeast corner of location, facing south. Photo of stormwater BMPs. Note inadequate surface roughening, downslope of stormwater control berm.



**Figure 16:** Photo taken from northeast corner of location, facing west. Photo shows disturbed areas exceeding stormwater BMPs.