

USA-Clark – Millison 1

Inspection# 673402729

Low berm.

12/8/2015

Inspection 673402729



Compromised and
overgrown berm.

11/18/2014

Inspection 673401414



Overgrown berm.

12/8/2015

Inspection 673402729



Overgrown berm.

11/18/2014

Inspection 673401414



Pit on east side of brown
tanks.

12/8/2015

Inspection 673402729



Pit on east side of brown
tanks.

11/18/2014

Inspection 673401414



No wellhead sign.

12/8/2015

Inspection 673402729



Equipment stored on location.

12/8/2015

Inspection 673402729



Equipment stored on
location.

11/18/2014

Inspection 673401414



Equipment stored on
location.

12/8/2015

Inspection 673402729



Equipment stored on
location.

11/18/2014

Inspection 673401414



Stained soil from pumpjack
exhaust.

12/8/2015

Inspection 673402729



Stained soil from pumpjack
exhaust.

11/18/2014

Inspection 673401414



Landfarm area.

12/8/2015

Inspection 673402729



Landfarm with sediment
leaving bermed area and
migrating off location.
Equipment storage in
background.

12/8/2015

Inspection 673402729



Landfarm area.

11/18/2014

Inspection 673401414

