

Interim Reclamation Inspection



Photo 1. Photo taken of well sign for 123-22832.

Interim Reclamation Inspection



Photo 2. Photo taken from northern location, facing South. Interim vegetative growth is representative of the reference area.

Interim Reclamation Inspection



Photo 3. Photo taken from western location, facing East. Interim vegetative growth is representative of the reference area.

Interim Reclamation Inspection



Photo 4. Photo taken from southern location, facing North. Interim vegetative growth is representative of the reference area.

Interim Reclamation Inspection



Photo 5. Photo taken from eastern location, facing West. Interim vegetative growth is representative of the reference area.

Interim Reclamation Inspection



Photo 6. Reference photo taken 50 meters northwest of 123-22832 . Reference area vegetative growth is representative of the interim area-123-22832.