

## Construction Inspection



**Photo 1.** Photo taken from west drill pad, facing West. Notice the slope funnels towards the northwest.



## Construction Inspection



**Photo 2.** Photo taken from west drill pad, facing North. Construction underway.



## Construction Inspection



**Photo 3.** Photo taken from west drill pad, facing Northeast. Construction underway.



## Construction Inspection



**Photo 4.** Photo taken from western area of west drill pad, facing West. Topsoil stockpile in center of photo.



## Construction Inspection



**Photo 5.** Photo taken from western area of west drill pad, facing South. Topsoil stockpile towards the right of the picture. Stormwater BMPs have not been installed prior to construction.



## Construction Inspection



**Photo 6.** Photo taken from northwestern area of west drill pad, facing North. Stormwater BMPs have not been installed prior to construction.



## Construction Inspection



**Photo 7.** Photo taken from northern area of west drill pad, facing West. Topsoil stockpile towards the right of the picture.