

Construction Inspection



Photo 1. Photo taken from western location, facing North. Stormwater BMP installed in center of photo. DO NOT scrape sediment into stormwater ditches. Stormwater ditches need to be maintained. Refer to close up photos 2-3.

Construction Inspection



Photo 2. Photo taken from western location, facing North. DO NOT scrape sediment into stormwater ditches. Stormwater ditches need to be maintained.

Construction Inspection



Photo 3. Photo taken from western location, facing North. DO NOT scrape sediment into stormwater ditches. Stormwater ditches need to be maintained.

Construction Inspection



Photo 4. Photo taken from western location, facing North. Only access/exit southern main location. Western vehicle traffic is damaging stormwater ditches. Stormwater ditches need to be maintained.

Construction Inspection



Photo 5. Photo taken from northern location, facing East. Topsoil stockpile located in center of photo.