

# Follow Up Inspection

12/21/2015

Operator: Wiepking-Fullerton

Location ID: 443145

API #: 05-073-06697

Lincoln County, CO

Section 2 T6S R54W

Aaron Trujillo  
Reclamation Specialist  
COGCC



**Figure 1:** Photo taken from Southwest of location, facing north. Photo of western drainage at location. Photo for monitoring purposes.





**Figure 2:** Photo taken from Southwest of location, facing northeast. Photo shows location and drill rig. Photo for monitoring purposes.





**Figure 3:** Photo taken from Southwest of location, facing east. Photo of southern drainage at location. Photo for monitoring purposes.





**Figure 4:** Photo taken from southeast end of location, facing north. Photo of stormwater BMPs





**Figure 5:** Photo taken from southeast end of location, facing northwest. Photo shows caged-trailer used for debris management. Note door to cage not properly shut.





**Figure 6:** Photo taken from southeast end of location, facing west. Photo shows caged-trailer used for debris management. Note door to cage not properly shut.





**Figure 7:** Photo taken from southern end of location, facing west. Photo of trash debris in project area.





**Figure 8:** Photo taken from southern end of location, facing south. Photo of trash debris on stormwater BMP.





**Figure 8:** Photo taken from eastern end of location, facing north. Photo of trash debris on stormwater BMP.





**Figure 10:** Photo taken from north end of location, facing northeast. Photo of trash debris.





**Figure 11:** Photo taken from north end of location. Photo of trash debris.





**Figure 12:** Photo taken from northeast end of location, facing west. Photo shows equipment being stored off-site of project area.





**Figure 13:** Photo taken at southern pit. Photo shows oily water. Pit does not appear to be lined.





**Figure 14:** Photo taken at southern pit. Photo shows oily water.





**Figure 15:** Photo taken at southern pit. Photo shows oily water. Pit does not appear to be lined.





**Figure 16:** Photo taken at southern pit. Photo shows oily water. Pit does not appear to be lined.





**Figure 17:** Photo taken at tanks on the south end of location. Photo shows containment BMP not properly functioning.





**Figure 18:** Photo taken at tanks on the south end of location. Photo shows containment BMP not properly functioning.





**Figure 19:** Photo taken at tanks on the south end of location. Photo shows containment BMP not properly functioning.





**Figure 20:** Photo taken from south end of location. Photo shows white chemical substance. Chemical had a smell similar to that of battery acid.





**Figure 21:** Photo taken from south end of location. Photo shows white chemical substance. Chemical had a smell similar to that of battery acid.





**Figure 22:** Photo taken from south end of location. Photo shows white chemical substance. Chemical had a smell similar to that of battery acid.