

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/23/2015

Document Number:

666801768

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	294181	335484	Murray, Richard	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 96850Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@wpxenergy.com	Field Inspections

**Compliance Summary:**QtrQtr: NESW Sec: 13 Twp: 6S Range: 94W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/03/2011	200302443	SR	PR	SATISFACTORY			No
07/02/2010	200263225	SR	PR	ACTION REQUIRED			No
06/22/2010	200277487	PR	PR	SATISFACTORY			No
02/25/2010	200232614	PR	PR	SATISFACTORY			No

**Inspector Comment:**Inspection if for wells with the status of Abandoned Location**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
294180	WELL	AL	05/27/2011	LO	045-15299	CLOUGH RWF 324-13	AL	<input checked="" type="checkbox"/>
294181	WELL	PR	08/01/2008	GW	045-15300	CLOUGH RWF 424-13	PR	<input type="checkbox"/>
294182	WELL	PR	08/30/2008	GW	045-15301	CLOUGH RWF 24-13	PR	<input type="checkbox"/>
294183	WELL	AL	05/27/2011	LO	045-15302	CLOUGH RWF 513-13	AL	<input checked="" type="checkbox"/>
294184	WELL	AL	05/27/2011	LO	045-15303	CLOUGH RWF 413-13	AL	<input checked="" type="checkbox"/>
294185	WELL	AL	05/27/2011	LO	045-15304	CLOUGH RWF 313-13	AL	<input checked="" type="checkbox"/>
294186	WELL	AL	05/27/2011	LO	045-15305	CLOUGH RWF 13-13	AL	<input checked="" type="checkbox"/>
294187	WELL	AL	05/27/2011	LO	045-15306	CLOUGH RWF 314-13	AL	<input checked="" type="checkbox"/>

Inspector Name: Murray, Richard

294188	WELL	AL	05/27/2011	LO	045-15307	CLOUGH RWF 414-13	AL	<input checked="" type="checkbox"/>
294189	WELL	AL	05/27/2011	LO	045-15308	CLOUGH RWF 514-13	AL	<input checked="" type="checkbox"/>
294190	WELL	PR	08/01/2008	GW	045-15309	CLOUGH RWF 23-13	PR	<input type="checkbox"/>
294191	WELL	AL	05/27/2011	LO	045-15310	CLOUGH RWF 323-13	AL	<input checked="" type="checkbox"/>
294192	WELL	AL	05/27/2011	LO	045-15311	CLOUGH RWF 423-13	AL	<input checked="" type="checkbox"/>
294193	WELL	AL	05/27/2011	LO	045-15312	CLOUGH RWF 523-13	AL	<input checked="" type="checkbox"/>

**Equipment:**

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

Emergency Contact Number (S/AR): \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Spills:**

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

**Venting:**

Yes/No	
Comment	

**Flaring:**

Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

**Predrill**

Location ID: 294181

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/AR:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

Data retrieval failed for the subreport 'Subreport1' located at: \\10.12.100.15\cFormReports\Insp\InspCOA.rdlx. Please check t

**S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:**

Data retrieval failed for the subreport 'Subreport2' located at: \\10.12.100.15\cFormReports\Insp\InspBMP.rdlx. Please check t

**S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 294180 Type: WELL API Number: 045-15299 Status: AL Insp. Status: AL

Facility ID: 294183 Type: WELL API Number: 045-15302 Status: AL Insp. Status: AL

Facility ID: 294184 Type: WELL API Number: 045-15303 Status: AL Insp. Status: AL

Facility ID: 294185 Type: WELL API Number: 045-15304 Status: AL Insp. Status: AL

Facility ID: 294186 Type: WELL API Number: 045-15305 Status: AL Insp. Status: AL

Inspector Name: Murray, Richard

Facility ID:	294187	Type:	WELL	API Number:	045-15306	Status:	AL	Insp. Status:	AL
Facility ID:	294188	Type:	WELL	API Number:	045-15307	Status:	AL	Insp. Status:	AL
Facility ID:	294189	Type:	WELL	API Number:	045-15308	Status:	AL	Insp. Status:	AL
Facility ID:	294191	Type:	WELL	API Number:	045-15310	Status:	AL	Insp. Status:	AL
Facility ID:	294192	Type:	WELL	API Number:	045-15311	Status:	AL	Insp. Status:	AL
Facility ID:	294193	Type:	WELL	API Number:	045-15312	Status:	AL	Insp. Status:	AL

### Environmental

#### Spills/Releases:

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
Comment: \_\_\_\_\_  
Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

#### Water Well:

Lat \_\_\_\_\_ Long \_\_\_\_\_  
DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

#### Field Parameters:

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_  
Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

The subreport 'rptInsp13' could not be found at the

#### Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666801768	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3747923">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3747923</a>