

Construction Inspection



Photo 1. Photo taken from southwestern location, facing Southeast. Topsoil stockpile in center of photo.

Construction Inspection



Photo 2. Photo taken from southwestern location, facing East. Stormwater BMP in center of photo.

Construction Inspection



Photo 3. Photo taken from south location, facing Northeast. Topsoil stockpile storage around perimeter of location.

Construction Inspection



Photo 4. Photo taken from southeast location, facing North. Stormwater BMP in center of photo.

Construction Inspection



Photo 5. Photo taken from eastern location, facing North. Stormwater BMP in center of photo.

Construction Inspection



Photo 6. Photo taken from eastern location, facing North. Stormwater BMP in center of photo.

Construction Inspection



Photo 7. Photo taken from northeast location, facing West. Stormwater BMP in center of photo.

Construction Inspection



Photo 8. Photo taken from northern location, facing South. Stormwater BMP in center of photo.

Construction Inspection



Photo 9. Photo taken from western location, facing South along access road. Operator plans to install gravel to minimize rutting and tracking, and control potential sediment discharge.