

## Interim Reclamation Inspection



**Photo 1.** Photo taken from northern entrance, facing Southwest. Interim reclamation area lacks perennial vegetative growth. Refer to photo 3.

## Interim Reclamation Inspection



**Photo 2.** Photo taken from northern entrance, facing Southeast.

## Interim Reclamation Inspection



**Photo 3.** Photo taken from southwest location, facing South. Interim reclamation lacks perennial vegetative growth. Need to manage undesirable plant species (tumbleweeds) to ensure perennial vegetative establishment and to control undesirable species from spreading onto other adjacent lands.

## Interim Reclamation Inspection



**Photo 4.** Photo taken from northern entrance, facing North. Need to stabilize and control erosion.

## Interim Reclamation Inspection



**Photo 5.** Photo taken of fenced in well area. Need to manage noxious weeds per COGCC 1003 rules.

## Interim Reclamation Inspection



**Photo 6.** Photo taken of fenced in well area. Need to manage noxious weeds per COGCC 1003 rules.

## Interim Reclamation Inspection



**Photo 7.** Reference photo taken east of location. Notice the uniform perennial vegetative growth.