

# Stormwater Inspection

1/4/2016

Operator: Western Operating

Location ID: 435387

Washington County, CO

CNW Section 9 T1S R56W

Aaron Trujillo

Reclamation Specialist

COGCC



**Figure 1:** Photo of sign taken at battery.



**Figure 2:** Photo taken from east end of location facing north. Photo shows stormwater and sediment control BMPs have not been installed.



**Figure 3:** Photo taken from east end of location. Initially though pile was a berm installed for stormwater management. After digging it was determined berm was a snow stock pile, not a stormwater and sediment control BMP.



**Figure 4:** Photo taken from east end of location, facing south. Photo shows stormwater and sediment control BMPs have not been installed.



**Figure 5:** Photo taken from north end of location, facing west. Photo of erosion and exposed pipe.



**Figure 6:** Photo taken from north end of location, facing south. Photo of erosion and exposed pipe.



**Figure 7:** Photo taken from northwest portion of location, facing south. Photo shows door to box-framed subsurface structure remains in disrepair.



**Figure 8:** Photo taken from southwest of pit location, facing north. Photo shows stormwater and sediment control BMPs have not been installed.



**Figure 9:** Photo taken from southwest end of pit location, facing northeast. Photo shows stormwater and sediment control BMPs have not been installed.



**Figure 10:** Photo taken southeast end of pit location, facing west. Photo shows stormwater and sediment control BMPs have not been installed.



**Figure 11:** Photo taken southeast end of pit location, facing north. Photo shows stormwater and sediment control BMPs have not been installed.



**Figure 12:** Photo taken from northeast end of pit location, facing south. Photo shows stormwater and sediment control BMPs have not been installed.



**Figure 13:** Photo taken northeast end of pit location, facing west. Photo shows stormwater and sediment control BMPs have not been installed.