

# Construction Inspection



**Photo 1.** Photo taken from northwest location, facing South. Stormwater BMPs installed in center of photo.

## Construction Inspection



**Photo 2.** Photo taken from northwest location, facing East. Stormwater BMPs installed in center of photo.

## Construction Inspection



**Photo 3.** Photo taken from northeast location, facing South. Stormwater BMPs installed in center of photo.

## Construction Inspection



**Photo 4.** Photo taken from southeast location, facing West. Stormwater BMPs installed in center of photo.

## Construction Inspection



**Photo 5.** Photo taken from southwest location, facing East. Stormwater BMPs installed in center of photo.

## Construction Inspection



**Photo 6.** Photo taken from the western location, facing Southeast. Topsoil stockpile stabilized.