

Construction Reinspection



Photo 1. Photo taken from southwestern location, facing North. Stormwater BMP installed in center of photo. All stockpiled soils shall be protected from degradation. The west-facing topsoil stockpile is steep and erodible. Refer to photo 2.

Construction Reinspection



Photo 2. Photo taken from southwestern topsoil stockpile, facing North. All stockpiled soils shall be protected from degradation. The west-facing topsoil stockpile is steep and erodible. May need to stabilize slope like the east-facing slope (Refer to Photo 3).

Construction Reinspection



Photo 3. Photo taken from southwestern topsoil stockpile, facing North. East-facing topsoil stockpile properly tracked and slope is not too steep.

Construction Reinspection



Photo 4. Photo taken from western location, facing North. Stormwater BMP in center of photo.

Construction Reinspection



Photo 5. Photo taken from northwest location, facing East. Stormwater BMP installed in center of photo.

Construction Reinspection



Photo 6. Photo taken from north-central location, facing North. Stormwater BMP installed in center of photo.

Construction Reinspection



Photo 7. Photo taken from north-central location, facing East. Stormwater BMP installed in center of photo.

Construction Reinspection



Photo 8. Photo taken from northeast topsoil stockpile, facing East. All stockpiled soils shall be protected from degradation and to maintain soil microbial activity shall be implemented. The north-facing topsoil stockpile is steep and erodible. Also, the topsoil stockpile is piled high which could negatively affect soil microbial activity. May need to stabilize and reduce the height of the pile to around 6' in the future.

Construction Reinspection



Photo 9. Photo taken from northeast topsoil stockpile, facing East. All stockpiled soils shall be protected from degradation and to maintain soil microbial activity shall be implemented. The south-facing topsoil stockpile is steep and erodible. Also, the topsoil stockpile is piled high which could negatively affect soil microbial activity. May need to stabilize and reduce the height of the pile to around 6' in the future.

Construction Reinspection



Photo 10. Photo taken from northeastern location, facing South. Stormwater BMP installed in center of photo.

Construction Reinspection



Photo 11. Photo taken from southeastern location, facing North. Stormwater BMP installed in center of photo.