

## Abandoned Location Inspection



**Photo 1.** Photo taken from center of location, facing West. It appears the location was never built.

## Abandoned Location Inspection



**Photo 2.** Photo taken from center of location, facing North. It appears the location was never built.

## Abandoned Location Inspection



**Photo 3.** Photo taken from center of location, facing East. It appears the location was never built.


## Abandoned Location Inspection



**Photo 4.** Photo taken from center of location, facing South. It appears the location was never built.



## Abandoned Location Inspection



**Photo 5.** Google Earth aerial photo taken 6/19/2014. It appears the location was never built based off aerial imagery and field observations.