



photo 1: Aerial photo of the location (6/2014).



photo 2: Facing east along the access road toward the location.



photo 3: Facing east along the access road toward the location.



photo 4: Tank battery remains near the west side of the location



photo 5: Tank was not properly labeled and did not have a sign. Tank does not appear to be in use.



photo 6: Facing west. Unused equipment is being stored near the tank battery.



photo 7: Facing east toward the location.



photo 8: Facing east toward the location. Manure has been spread over the location.



photo 9: Pipe riser remains at the center of the location. Lat/Long:37.95992,-102.50066



photo 10: North side of the location facing south.



photo 11: Facing southwest toward the tank battery and the compressor.



photo 12: Unused pipe was found between the compressor and the tank battery.