



**photo 1:** Well sign at the beginning of the access road at the county road.



**photo 2:** Beginning of the access road facing southwest.



**photo 3:** Cattle guard at beginning of the access road is not maintained.



**photo 4:** Evidence of rutting occurring along the access road.



**photo 5:** Access is not being restricted along the access road. Evidence of rutting exists.



**photo 6:** Area adjacent to the access road looks to have been regraded since the previous inspection.



**photo 7:** No vegetation has established along the disturbed area adjacent to the access road.



**photo 8:** Northeast corner of the location facing southwest. Note: the east side of the location has not been recontoured.



photo 9: Facing southwest toward the location.



photo 10: Fence around the tank battery is in disrepair.



**photo 11:** There is an area (~3'x1') of oil stained soil next to the tank battery.



**photo 12:** Facing east from the northwest corner of the location.