



photo 1: Facing south toward the location..



photo 2: Location where pipe riser was noted in the previous inspection has been removed.



photo 3: Location where pipe riser was noted in the previous inspection has been removed.



photo 4: Area at the center of the location with minimal vegetation growth.



photo 5: Area of subsidence found at the location. Lat/Long:37.93085,-102.69283



photo 6: Plywood debris remains at the west side of the location.