



**photo 1:** Pipe riser remains near the access road.



**photo 2:** Pipe riser remains at the north side of the location.





**photo 3:** Center of the location facing north.



**photo 4:** Center of the location facing west.





**photo 5:** Center of the location facing south.



**photo 6:** Center of the location facing east.





**photo 7:** West side of the location. Borrow area has not been recontoured and reclaimed..



**photo 8:** South side of the location facing north.





**photo 9:** Facing east at the location. Shovel was used to determine compaction. Soils were heavily compacted throughout the site.



**photo 10:** Surrounding undisturbed pasture. Facing west.