



photo 1: (6/2014) Aerial image of the location. Red arrow indicates approximate point of access road.



photo 2: Facing west along the access road towards the location.



photo 3: Facing west toward the location.



photo 4: Blanket has been installed east portion of the location.



photo 5: Vegetation appears to be establishing where the blanket has been installed.



photo 6: Facing west at the location.



photo 7: Center of the location facing north.



photo 8: Vegetation does not appear to be establishing where the blanket was not installed.



photo 9: West side of the location facing east. Blanket was not installed at the east side of the location.



photo 10: West side of the location facing east.



photo 11: Facing east toward the south part of the location. Vegetation is not establishing.



photo 12: Surrounding undisturbed vegetation.