



photo 1: (6/2014) Aerial image of the location.



photo 2: Facing southeast toward the location where straw blanket was installed.



photo 3: North side of the location facing south.



photo 4: Straw blanket is in disrepair at the northeast corner of the location.



photo 5: Vegetation appears to be establishing where the blanket has been installed.



photo 6: South side of the location facing north.



photo 7: : Straw blanket is in disrepair at the south side of the location.



photo 8: Northwest corner of the location. Vegetation is not establishing where straw blanket was not installed.