



photo 1: Aerial image of the location (6/2014).



photo 2: Former access road facing south towards the location.



**photo 3:** North side of the location facing southeast.



**photo 4:** One of two pipe risers that remain at the location. Lat/Long:37.09063,-102.48639.



**photo 5:** Second pipe riser that remains at the location. Lat/Long:37.90937,-102.48610.



**photo 6:** South side of the location facing north.



**photo 7:** Center of the location facing north. Note: Vegetation has not reestablished in this area.



**photo 8:** Facing toward the northeast corner of the location. Note: Vegetation has not reestablished in this area



**photo 9:** Facing east off of the northeast corner of the location.



**photo 10:** Facing west toward the surrounding undisturbed pasture. Reference area.