

Enforcement: 1120973  
 Enforcement: 1187959  
 Project: 1801  
 Document #: 2211347  
 Date: 09/25/2002

## COGIS - Field Inspection Report

	
API Number: <b>05-001-05542</b>	Name: <b>SIMPSON A #4</b>
Location: <b>SENE 12 1S 58W</b>	Lat: <b>39.981528</b> Long: <b>-103.818583</b>
Operator #: <b>31257</b>	Operator Name: <b>FRITZLER RESOURCES INC</b>
Inspection Date: <b>9/25/2002</b>	Inspector: <b>Randall Ferguson</b>

Inspection was: **Unsatisfactory**

Insp. Type: **ES**      Insp. Stat: **PR**      Reclamation (Pass, Interim or Fail): **F**      P&A (Pass/Fail): **F**  
 Brhd. Pressure:      Inj. Pressure:      T-C Ann. Pressure:      UIC Violation Type:  
 Violation: **Y**      NOAV Sent: **Y**      Date Corrective Action Due: **1/15/2004**      Date Remedied:

### Field Inspection Comments and Observations

Insp. Comment	Inspection/Violation Comments
ACTION	SUBMIT A FORM 27 - SITE INVESTIGATION AND REMEDIATION WORKPLAN FOR THE REMEDIATION AND RECLAMATION OF THE PRODUCED WATER IMPACTED SOILS.
SPILCOM	PRODUCED WATER IMPACTED SOILS OBSERVED AT FORMER PIT LOCATION. LAB RESULTS OF REPRESENTATIVE SAMPLE INDICATE SOIL CONDITIONS THAT EXCEED THE COGCC STANDARDS FOR INORGANICS IN SOILS.
SURFRH	FORMER PIT AREA AND PRODUCED WATER IMPACTED SOILS NEED TO BE REMEDIATED AND RECLAIMED.