

Inspection Photos
Berry Energy Compressor Facility
Lat/Long: 37.960289, -102.501992
2/5/16



Figure 1 – West side of compressor station



Figure 2 – Free product and stained soil on west side of compressor.



Figure 3 – Oily rags on northwest corner of compressor station.



Figure 4 – Stained soil on northeast corner of compressor.



Figure 5 – Leaking barrels stored on location



Figure 6 – Lube oil drain bucket on west side of compressor station.



Figure 7 – West side of compressor station.



Figure 8 – Oil stained soil on east side of the compressor.