

# Interim Reclamation Inspection

2/9/2016

Operator: Whiting Oil and Gas

Location ID: 430695

Weld County, CO

NWNW Section 22 T10N R58W

Aaron Trujillo

Reclamation Specialist

COGCC



**Figure 1:** Photo well sign at 123-36257.



**Figure 2:** Photo of sign at well 123-38508



**Figure 3:** Photo of sign at well 123-38510



**Figure 4:** Photo of sign at 123-38507.



**Figure 5:** Photo taken from location, facing west. Note stake marking well location as not been removed.



**Figure 6:** Photo taken from east end of location. Photo of tracking BMP.



**Figure 7:** Photo taken from northeast end of location, facing west. Photo of stored cuttings and waddles.



**Figure 8:** Photo taken from northeast end of location, facing west.



02.09.2016 11:51

**Figure 9:** Photo taken from northeast end of location, facing south. Photo shows interim and project areas.



**Figure 10:** Photo taken topsoil berm on the east end of the location, facing south. Photo of vegetation on interim area.



**Figure 11:** Photo taken from topsoil berm on the east end of the location, facing south. Photo of vegetation on interim area, and stormwater control.



**Figure 12:** Photo taken from east end of project location. Photo of what appears to be a tarp covered in snow on ground.



**Figure 13:** Photo taken from the east end of the interim location, facing east. Photo of trash debris.



**Figure 14:** Photo taken from southeast end of location, facing north. Photo of project and interim areas.



**Figure 15:** Photo taken from southeast end of location, facing west. Photo of project and interim areas.



**Figure 16:** Photo taken from east end of location, facing south. Photo of drill cuttings and waddles.



**Figure 17:** Photo taken from southeast end of location, facing west. Photo of drill cuttings and waddles.



**Figure 18:** Photo taken from southern end of location, facing east. Photo of drill cuttings and waddles.



**Figure 19:** Photo taken from southern end of location, facing northwest. Photo of trash debris on interim area. Trash debris appears to be orange plastic fencing.



**Figure 20:** Photo taken from southern end of location. Photo of trash debris on interim area. Trash debris appears to be trash can lid.



**Figure 21:** Photo taken from southwest end of location, facing north. Photo of interim and project areas.



**Figure 22:** Photo taken from southwest end of location, facing east. Photo of interim and project areas.



**Figure 23:** Photo taken from southwest corner of project location. Photo of what appears to be a rolled tarp improperly stored.



**Figure 24:** Photo taken from southwest corner of location, facing east. Photo of interim and project areas.



**Figure 25:** Photo taken from southwest corner of location, facing north.



02.09.2016 12:08

**Figure 26:** Photo taken from southwest corner of location, facing north.