**Falcon Seaboard 11-90-12 #3:**

- 1A Surface Location
 39.11235° N 1824 FSL
 107.39928° W 1874 FWL
- 1B Bottom Hole Location
 39.11993° N 684 FNL
 107.40568° W 59 FWL

Falcon Seaboard 11-90-12 #5:

- 2A Surface Location
 39.11249° N 1876 FSL
 107.39947° W 1821 FWL
- 2B Bottom Hole Location
 39.10021° N 2607 FNL
 107.39010° W 881 FEL

Falcon Seaboard 11-90-12 #6:


- 3A Surface Location
 39.11239° N 1838 FSL
 107.39923° W 1888 FWL
- 3B Bottom Hole Location
 39.11985° N 721 FNL
 107.39915° W 1913 FWL

Falcon Seaboard 11-90-12 #7:

- 4A Surface Location
 39.11253° N 1891 FSL
 107.39942° W 1835 FWL
- 4B Bottom Hole Location
 39.09756° N 1689 FSL
 107.38955° W 732 FEL

Note:

- ~ FNL, FSL, FEL and FWL is the footage to the nearest section line measured perpendicularly. (i.e. feet North to Line)
- ~ Horizontal Datum = NAD83



SURFACE LOCATION DETAIL:
 Not to Scale

LEGEND

- ◆ ~ FOUND ORIGINAL STONE
- ◆ ~ FOUND GLO BRASS CAP ON STEEL POST
- ⊕ ~ FOUND REBAR AND CAP BY LS15710
- ~ FOUND No.6 REBAR WITH A 2 1/2" ALUMINUM CAP, LS24963
- ~ WELL FEATURES



Scale: 1" = 2000 U.S. Survey feet

MULTIWELL LOCATION PLAT

SG INTERESTS I, LTD.
 FALCON SEABOARD 11-90-12 # 3, 5, 6 & 7
 SW 1/4 Section 12, T. 11 S., R. 90 W., 6th P.M.,
 Gunnison County, Colorado

SURVEYED BY:
 DGN

DRAFTED BY:
 MLD

DWG DATE:
 02/08/2016

SCALE:
 1" = 2000'

AECOM
 David G. Nicewicz, PLS
 804 Colorado Ave, Suite 201 Glenwood Springs Co 81610
 cell: (720) 456-1104 email: david.nicewicz@aecom.com

JOB NO.: 22243490.14000

SHEET NO. 1 of 1