

# Interim Reclamation Inspection

2/9/2016

Operator: Whiting Oil and Gas

Location ID: 431115

Weld County, CO

NWNE Section 21 T10N R58W

Aaron Trujillo

Reclamation Specialist

COGCC



**Figure 1:** Photo taken from stockpile on the southeast end of location, facing west. Photo shows location, current access road being used (yellow line), and drill cuttings (red arrow).



**Figure 2:** Photo taken from stockpile on the southeast end of location, facing northwest. Photo of location.



**Figure 3:** Photo taken from southeast portion of location, facing southwest. Photo of drill cuttings stored on location.



**Figure 4:** Photo taken from southwest portion of location, facing southeast. Photo of drill cuttings stored on location. Note pooling water on location/access road.



**Figure 5:** Photo taken from southwest corner of location, facing north. Photo shows topsoil stockpile on left side of photo, and drill cuttings on the right side of photo. Note lack of vegetative growth on topsoil berm.



**Figure 6:** Photo taken from topsoil stockpile on the west end of location. Photo shows vegetation is predominantly undesirable weedy vegetation.



02.09.2016 13:32

**Figure 7:** Photo taken from topsoil stockpile on the west end of location. Photo shows lack of vegetative growth.



**Figure 8:** Photo taken from topsoil stockpile on the west end of location, facing east. Photo shows project area and drill cuttings.



**Figure 9:** Photo taken from topsoil stockpile on the west end of location, facing southeast. Photo shows erosion occurring on topsoil stockpile, indicating lack of stabilization.



**Figure 10:** Photo taken from northwest corner of location, facing south. Photo shows drill cuttings on location, and topsoil berm. Note lack of vegetative growth on berm and rill erosion.



**Figure 11:** Photo taken from northwest corner of location, facing east. Photo shows project location yet to be reduced in size per interim reclamation requirements. Old ruts within area along yellow line indicated evidence of former use as an access road). Current access road is on the southern portion of the location.



**Figure 12:** Photo taken the north end of location, facing southeast. Photo shows project location, and topsoil berm (yellow arrow). Note height of berm is excessive, adequate room exists to have extended its length to the north, thus reducing the height. Arrow indicates vehicle for reference.



**Figure 13:** Photo taken from north end of location, facing south. Photo shows gully erosion beginning to encroach off project location.



**Figure 14:** Photo taken from northeast corner of location, facing south. Note height of berm is excessive, adequate room exists to have extended its length to the north, thus reducing the height.



**Figure 15:** Photo taken from northeast corner of location, facing west. Photo shows project location (left of line), and interim area (right of line). Note location has yet to be reduced in size per interim reclamation requirements. Old ruts within area along yellow line indicated evidence of former use as an access road.




**Figure 16:** Photo taken from well #123-37765.



02.09.2016 13:41

**Figure 17:** Photo taken from well 123-37767




**Figure 18:** Photo taken from well #123-39531



**Figure 19:** Photo taken from well #123-39534



**Figure 20:** Photo taken from well #123-39532.



**Figure 21:** Photo taken from well #123-39529



**Figure 22:** Photo taken from well #123-37978



**Figure 23:** Photo taken from well #123-37766



**Figure 24:** 2013 aerial image of location. Approximate area of project location (conservatively), not including total disturbed area, is 8.5 acres.



**Figure 25:** 2013 aerial image of location. Note the total area disturbed appears greater than 10.28 acres stated in the 2A (Doc. # 400437664) permitted area.