

Interim Reclamation Inspection

2/17/2016

Operator: Atlas Resources

Location ID: 425495

API: 095-06365

Phillips County, CO

NWSW Section 5 T8N R43W

Aaron Trujillo

Reclamation Specialist

COGCC



ATLAS ROCKIES LLC
BLACK RAVEN ENERGY - 10203
BEAL FEDERAL 843-5-13
NWSW, SEC.5-T8N-R43W
PHILLIPS COUNTY, CO
05-095-06365-COC65943
EMERGENCY 911 OR 303-308-1330

02.17.2016 11:42

Figure 1: Photo of sign at well.



Figure 2: Photo taken from the southwest end of location, facing north. Photo shows project area and vegetation on interim area.



Figure 3: Photo taken from the west end of interim area. Note vegetation is sparse and predominantly undesirable weedy vegetation.



Figure 4: Photo taken from the west end of location. Photo shows interim area predominantly dominated by undesirable weedy vegetation.



Figure 5: Photo taken from the western interim area. Photo shows bare area and vegetation on interim area.



Figure 6: Photo taken from the northwest end of location, facing south. Photo shows vegetation on interim area predominantly undesirable weedy vegetation.



Figure 7: Photo taken from the northwest end of location, facing east. Photo shows vegetation on interim area predominantly undesirable weedy vegetation.



Figure 8: Photo taken from the northeast end of location, facing west. Photo shows vegetation on interim area predominantly undesirable weedy vegetation.



Figure 9: Photo taken from the southeast end of location, facing north. Photo shows vegetation on interim area predominantly undesirable weedy vegetation.



Figure 10: Photo taken from the southeast end of location, facing west. Photo shows vegetation on interim area predominantly undesirable weedy vegetation.



Figure 11: Photo taken from the east end of project area, facing west. Photo shows stormwater erosion on location. Arrows shows water movement patterns and alluvial deposition.



Figure 12: Photo taken from the southern end of location, facing north. Photo shows erosion patterns on project area.



Figure 13: Photo taken from eastern end of the project area, facing west. Photo shows erosion patterns on location.



Figure 14: Photo taken from the central portion of the location, facing west. Photo shows erosion patterns on location.



Figure 15: Photo taken from the northwest end of location, facing south. Photo shows erosion occurring at pump.



02.17.2016 11:56

Figure 16: Photo taken from county road 51, west of location, facing east towards location. Photo of water pooling on access road.