



photo 1: Facing southeast toward the location. (Afton well)



photo 2: Facing south toward the location. (Pulis well)



photo 3: Well sign at the Pulis well.



photo 4: Unused equipment, a cattle guard was noticed near the Pulis well.



photo 5: Unused equipment, pipe being stored at the southwest corner of the location.



photo 6: Facing east toward the location. There is water pooling throughout the location.



photo 7: The Afton well head. Did not notice a sign at the well head.



photo 8: Northeast corner of the location facing west.



photo 9: Signs of erosion occurring off the north side of the pad which is not adequately stabilized.



photo 10: Facing northwest at the north side of the location. Disturbance is susceptible to erosion and needs to be reclaimed.



photo 11: Northwest corner of the location facing northwest toward the tank battery.



photo 12: There is vehicle rutting occurring along the access road near the tank battery.



photo 13: Vehicle tracking and rutting occurring near the tank battery and access road.



photo 14: Facing southeast back toward the location from the tank battery site.