



photo 1: Facing west at the beginning of the access road to the location.



photo 2: The access road has not been recontoured and reclaimed. Gravel remains along the access road.



Photo 3: Plastic culvert remains along the access road.



Photo 4: Facing northwest toward the location.



Photo 5: Operator sign at the location.



Photo 6: Electrical panel remains at the southeast side of the location.



Photo 7: North side of the location facing south.



Photo 8: North side of the location facing southwest. The location has not been recontoured.



Photo 9: What appears to be a Russian olive tree (List B noxious weed) at the northwest side of the location.



Photo 10: Diffuse knapweed (List B noxious weed) was noticed along the access road and at the location.



Photo 11: Stormwater BMP's at the west side of the location.



Photo 12: Waddle at the southwest corner of the location.