



**photo 1:** Facing northeast at the beginning of the access road to the location.



**photo 2:** Facing northeast toward the location.



**photo 3:** Facing east toward the location. The location has not been recontoured.



**photo 4:** East side of the location facing west. The location has not been recontoured.



photo 5: South side of the location facing northwest.



photo 6: Erosion channel formed at the south side of the location.



**photo 7:** Southwest corner of the location facing northeast.



**photo 8:** Surrounding undisturbed reference area.