

Interim Reclamation Inspection

2/17/2016

Operator: Atlas Resources

Location ID: 314139

API: 095-06231

Phillips County, CO

NESE Section 36 T9N R44W

Aaron Trujillo
Reclamation Specialist
COGCC



Figure 1: Photo taken from access road, facing north. Photo shows gas meter run on the east end of location.



02.17.2016 13:59

Figure 2: Photo of gas meter run on the east end of the location, facing north. Photo shows location was recently inundated with water. White substance (arrow) appears to be pieces of styrofoam.



Figure 3: Photo facility on the east end of the location, facing southeast. Photo shows erosion occurring at gas meter run. White substance at arrow appears to be pieces of styrofoam.



Figure 4: Photo facility on the east end of the location, facing west. Photo shows erosion occurring at gas meter run. White materials at arrow appears to be pieces of styrofoam.



Figure 5: Photo taken from the east end of location, facing west. Photo shows erosion at gas meter run. White materials at arrow appears to be pieces of styrofoam.



Figure 6: Photo taken from the east end of location, facing northeast. Photo shows erosion at gas meter run. White material appears to be pieces of styrofoam.



ATLAS ROCKIES LLC
BLACK RAVEN ENERGY-10203
OLTJENBRUNS STATE 944-36-43
NESE, SEC.36-T9N-R44W
PHILLIPS COUNTY, CO
05-095-06231
EMERGENCY 911 OR 303-308-1330

02.17.2016 14:03

Figure 7: Photo taken at well. Photo of sign at pump.



Figure 8: Photo taken from the southeast corner of well location, facing north. Photo shows vegetation on interim area, and project area.



Figure 9: Photo taken from the southeast corner of location, facing west. Photo shows vegetation on interim area, and project area.



Figure 10: Photo taken from the southwest corner of location, facing east. Photo shows vegetation on interim area, and project area.



Figure 11: Photo taken from the southwest corner of location, facing north. Photo shows vegetation on interim area, and project area.



Figure 12: Photo taken from the west end of location, facing east. Photo shows vegetation on interim area, and project area.



Figure 13: Photo taken the northwest end of project area, facing south. Photo shows vegetation on interim area, and project area.



Figure 14: Photo taken the northwest end of project area, facing east. Photo shows vegetation on interim area, and project area.



Figure 15: Photo taken northeast of project area, facing west. Photo shows vegetation on interim area, and project area.



Figure 16: Photo taken northeast of project area, facing south. Photo shows vegetation on interim area, and project area.



Figure 17: Photo taken east of well location, facing west. Photo shows vegetation on interim area, and project area.