

Photo#1:
Overview of Location to North



Photo#2:
Overview of Location to East



Photo#3:

Point where Net fencing begins at SE corner of Location.



Photo#4:

Net Fencing encircles Location on three Sides.



Photo#5:

Entrance to Location, downed Barbed wire fence.



Photo#6:

Lease Location Sign.



Photo#7:

Small Gravel pile on Location.



Photo#8:

Erosion, Run on at Fence disturbance site.



Photo#9:

Photo#10:

Run Off from Location causing Erosion Channels



Photo#11:

Un Reclaimed Access Road leading out of Location to SE .



Photo#12:

Access Road into Location , View NW.

