



Photo 1. View of unused culverts in southeastern portion of the project area.



Photo 2. View of cement debris in southeastern portion of the project area.



Photo 3. View of the project area from the northeastern corner facing center.



Photo 4. View of the northern portion of the project area from the northeastern corner facing westward. Vegetation is largely comprised of weedy kochia (*Kochia scoparia*) and intermediate wheatgrass (*Thinopyron intermedium*).



Photo 5. View of the western portion of the project area facing southward. Vegetation here is largely comprised of kochia debris.