

Construction and Stormwater Inspection

2/22/2016

Operator: Grand Mesa Operating

Location ID: 443491

API #: 121-11056

Washington County, CO

SESW Section 24 T2S R51W

Aaron Trujillo
Reclamation Specialist
COGCC



Figure 1: Photo taken from access road, south of location facing north. Photo of construction in process. Note stormwater and sediment control BMPs not in place.



Figure 2: Photo taken from access road, south of location facing west. Photo of access road.



Figure 3: Photo taken from access road, south of location facing east. Photo of access road.



Figure 4: Photo taken from access road, south of location facing northeast. Photo of location.



Figure 5: Photo taken from access road, south of location facing north. Photo of location.



Figure 6: Photo taken from access road, south of location facing northwest. Photo of location.



Figure 7: Photo taken from the southwest corner of location, facing east. Photo shows perimeter stormwater and sediment controls have not been installed.



Figure 8: Photo taken from the southwest corner of location, facing north. Photo shows perimeter stormwater and sediment controls have not been installed.



Figure 9: Photo taken from the southeast corner of location, facing north. Photo shows perimeter stormwater and sediment controls have not been installed.



Figure 10: Photo taken from the southeast corner of location, facing west. Photo shows perimeter stormwater and sediment controls have not been installed.



Figure 11: Photo taken from the east end of location, facing west. Photo shows perimeter stormwater and sediment controls have not been installed.



02.22.2016 13:57

Figure 12: Photo taken from the northeast corner of location, facing south. Photo shows perimeter stormwater and sediment controls have not been installed.



Figure 13: Photo taken from the northeast corner of location, facing west. Photo shows perimeter stormwater and sediment controls have not been installed.



Figure 14: Photo taken from the northwest corner of location, facing east. Photo shows perimeter stormwater and sediment controls have not been installed.



Figure 15: Photo taken from the northwest corner of location, facing south. Photo shows perimeter stormwater and sediment controls have not been installed.



Figure 7: Photo taken from the west end of the location, facing northeast. Photo shows perimeter stormwater and sediment controls have not been installed.