

Field Inspection Photos  
2/23/16  
Berry Energy  
099-06872



Figure 1 – Lease sign.



Figure 2 – Improperly stored materials and stained soil have been removed.



Figure 3 – Leak in produced water tank has been repaired and stained soil removed.