

Final Reclamation Inspection



Photo 1. Photo taken west of location, facing East. Apparent evidence of well location in agricultural field.

Final Reclamation Inspection



Photo 2. Photo taken from north well location, facing Southwest. Well location not properly reclaimed-not recontoured and waste material left behind.

Final Reclamation Inspection



Photo 3. Photo taken from north well location, facing South. Well location not properly reclaimed-not recontoured and waste material left behind.

Final Reclamation Inspection



Photo 4. Photo taken from north well location, facing East. Well location not properly reclaimed-not recontoured and waste material left behind.

Final Reclamation Inspection



Photo 5. Photo taken west of location, facing North. Demonstrates current land use and reference photo.