

Field Inspection Photos  
2/17/16  
Prowers Gas Gathering  
Facility 444661



Figure 1 – West side of facility



Figure 2 – Soil stained six to eight inches deep.



Figure 3 – Oily rags discarded on northwest corner of compressor.



Figure 4 – Barrels leaking and stained soil on east side of compressor.



Figure 5 – Stained soil on east side of compressor.



Figure 6 – Compressor leaking oil on west side of facility.



Figure 7 – Leaking barrels of motor oil stored on site.